

Parts & Service Update

No. 2017-02 January, 2017

Model 5313/5326 Common Actuator Piston & Housing Update

As of September 2013*, all rail brake models use the same common actuator piston adjusting screw. As of November 2014**, all rail brake models now use the same common housing. Jacobs' part numbers have not been changed, but Navistar has issued new part numbers. Replacement part numbers may not match the current brake, but the new actuator piston is backwards compatible. As of December 2015***, the Navistar sub-assembly part numbers have been revised. Reference the chart below for updated part numbers.

AFFECTED NAVISTAR MODELS			
MODEL / ENGINE	PART NUMBER		DESCRIPTION
	JVS	NAVISTAR	DESCRIPTION
5313 12VDC I-313 / I-341 Engines	38053	Old 1847786C96 Old 1847786C97* Old 1847786C98** New 1847786C99***	Rail Assembly Final 12VDC
5313 24 VDC I-335 Engine	37135	Old 1847989C96 Old 1847989C97* Old 1847989C98** New 1847989C99***	Rail Assembly Final 24VDC
5326 12VDC I-326 Engine	35302	Old 1833945C95* Old 1833945C96** New 1833945C97***	Rail Assembly Final 12VDC