



Service Letter

Service Letter No. 405 September, 1994

SUBJECT: Jake Brake® Tune-up Kits

MODELS AFFECTED: 750/760A/765

Effective immediately, Jacobs has released new Tune-up Kit part numbers for Jake Brake® Models 750 and 760A/765. These new part numbers contain new POWER-LASH® Assemblies, P/N 020382, in place of P/N 015931, Reset Screw Assemblies (Reference Jacobs Service Letter No. 399).

The part number changes are as follows:

| Tune-up Kit | Old Part Number | New Part Number |
|--------------------|------------------------|------------------------|
| Model 750 | 019766 | 020530 |
| Model 760A/765 | 019847* | 020531 |

* Please note that this is the correct part number for the Model 760A/765 tune-up kit. Service Letter No. 399 erroneously identified the incorrect part number for this Tune-up Kit .

There is no change to the Model 760 Tune-up Kit, P/N 019875.

Inventory of P/N 019766 and 019847 Tune-up Kits should be returned for credit to your Jacobs Warehouse Distributor following the standard return material procedure.

This is a Jacobs product improvement and not subject to campaign.