

# Service Letter

**Service Letter No. 411**  
**October, 1994**

**SUBJECT: New Base Support**


**MODELS AFFECTED: 346D and 349A**

Jacobs has introduced a new Base Support, P/N 019031, which replaces both the P/N 016939 (for the Model 346D) and P/N 017981 (for the Model 349A) base supports. Despite its compact design, the new support is stronger than either of its predecessors. The installation of the new support is the same as previous supports (refer to the Model 346D Installation Manual, P/N 017317, or the Model 349A Installation Manual, P/N 018312).


The P/N 019031 Support is fully interchangeable with the other supports and may be mixed with them on an engine.

Any inventory of the P/N 016939 or 017981 Base Supports should be used up. New orders for these parts should be replaced by the P/N 019031 Base Support.

This is a Jacobs product improvement and not subject to campaign.



Base Support  
P/N 016939/017981



Base Support  
P/N 019031