



Jacobs Vehicle
Equipment Company

Service Letter

**Service Letter No. 415
December, 1994**

SUBJECT: Control Valve Inner Spring Change

MODELS AFFECTED: C317, C317A, 317B, 317C, 310

Jacobs has replaced the yellow inner control valve spring, P/N 018179, with a blue inner control valve spring, P/N 019504, for all Model 317 Series and Model 310 applications. This change affects the Control Valve Group, P/N 018699, as well as the 317 Series Tune-up Kit, P/N 018158, as of September, 1993. The change was made to improve the durability of the spring. The yellow spring, P/N 018179, will continue to be used on other brake models.

If a failure of the yellow spring, P/N 018179, occurs in any of the 317 Series Jake Brake® models, all six (6) springs should be replaced with blue springs, P/N 019504.

This is a Jacobs product improvement and not subject to campaign.