

lacobe Engine Brake

Service Letter E487	
SUBJECT: INCORRECTLY MARKED NAMEPLATES	
MODELS AFFECTED: 760B	
DATE: December 1, 1998	
Introduction	
The housing nameplate for the 12VDC 3 Housing Model 760B Kit was incorrectly printed. This affects housings with this designation manufactured prior to Decemb 1998. The nameplate incorrectly states that the model is applicable to 12 .7 Liter engines. Model 760B is only applicable to 1998 11.1 Liter engines.	per 1,
Impact	
If a 760B Engine brake housing is installed on a 12.7 Liter engine, engine and/or engine brake damage will result. This situation might happen if an engine brake removed from a 1998 11 .1 Liter engine, and installed on a 12.7 Liter engine.	
Service Information	
When installing a used engine brake on an engine, confirm the correct Jacobs Er Brake application and lash setting using a current Jacobs Engine Brake Application guide (part number 24770) or Detroit Diesel Series 60 service manual (part number 6SE640). Do not apply 760B to 12.7 Liter engines.	on
As a preventative measure, it is advised that the characters 12.7L"be removed from nameplate if the valve covers are removed for another service reason. This can done by scratching with a punch or other sharp object.	
Obsolescence	
No part numbers have been made obsolete as a result of this change.	
Warranty Information	
The standard Jacobs Vehicle Systems warranty applies.	

No products are subject to campaign as a result of this service letter.