

Parts & Service Update

No. 2020-01 January, 2020

Jacobs Aftermarket Kits for Cummins ISL Engines Models Affected: ISC/ISL/L9

To retrofit ISL engines with a Jacobs Engine Brake[®], Jacobs offers aftermarket kits. In addition to the kits listed below, contact your local Cummins' dealer for additional Cummins' parts required for installation.

OPTIONS FOR ISC / ISL ENGINES		
	OPTION TO BE REMOVED	OPTION TO BE INSTALLED
ISC / ISL CM2150 (2007 EPA)	BR9296	BR9297
	ER9058	ER9059
	RL9777	RL9778
	VC9361	VC9364
		EB9038
ISC / ISL CM2250 (2010 EPA)	BR9300	BR9301
	ER9142	ER9143
	RL9777	RL9778
	VC9469	VC9470
		EB9038
ISL CM2350 (2013 EPA)	BR9300	BR9301
	ER9142	ER9143
	RL9815	RL9816
	VC9469	VC9470
		EB9038
L9 CM2350 (2017 EPA)	BR9300	BR9301
	ER9327	ER9326
	RL9815	RL9816
	VC9469	VC9470
	VC9471	VC9472
		EB9038