



# *Service Letter*

---

**Service Letter No. 406  
October, 1994**

**SUBJECT: Application on International 8100 with Detroit Diesel  
Series 50 Engines**

**MODELS AFFECTED: Model 750**

Be advised that Jacobs Vehicle Equipment Company does not recommend application of the Jake Brake® Model 750 on International 8100 vehicles with Detroit Diesel Series 50 engines. This recommendation is due to insufficient overhead height between the engine and the vehicle which does not allow room for the engine brake.