



Jacobs Engine Brake™ Service Letter E482

SUBJECT: Vented Control Valve Cover

MODELS AFFECTED: Model 455 series

DATE: August 1, 1998

Introduction _____

Jacobs Vehicle Systems is pleased to announce the release of Vented Control Valve covers for the Cummins 455 series engine brakes. The new covers allow the oil to exit the cover faster.

Impact _____

The new control valve cover is a direct replacement for the older style. New brakes will be shipped with the new style control valve cover as of August 3, 1998. When ordering a control valve cover for Models 455A, 455B, and 455C the new vented cover should be used.

Availability _____

The new part numbers will be available as follows:

Cummins New Parts Numbers	Jacobs New Part numbers	Description	Availability Date
3412330	026170	Control Valve Cover	8/10/98
3871704	020923*	Tune-up Kit	8/10/98

* Has Not Changed

New Part Numbers _____

Cummins Old Part Numbers	Jacobs Old Part Number	Cummins New Part Numbers	Jacobs New Part Numbers	Description
3871365	011252	3412330	026170	Control Valve Cover
3871657	020923	3871704	020923*	Tune-up Kit

* Has Not Changed

SERVICE LETTER E482

SERVICE LETTER E482

Service Information

The installation of the Control Valve cover is the same as previous cover. Please see Cummins Installation Manual, Bulletin 3698823 for instructions.

Obsolescence

No parts have become obsolete as a result of this product release. Inventory of P/N 3871557 (011252) should be used on models other than the 455 series engine brakes.

Warranty Information

The standard warranty applies.